



### Available Stages

Shortcut	Command	Image Acquisition	Virtual Model	Preparation Margin	Insertion Axis	Design	Milling Preview
<Return>	Next	X	X	X	X	X	
<Ctrl> + O	Load Restoration	X	X	X	X	X	X
<Ctrl> + B	Toggle model box (Opens model from bottom)		X	X	X	X	
<Ctrl> + S	Save	X	X	X	X	X	X
<Ctrl> + Z	Undo		X	X	X	X	X
<Ctrl> + N	New Restoration	X	X	X	X	X	X
<Ctrl> + H	Toggle high/low resolution model (no effect on milling)		X	X	X	X	
<Ctrl> + R	Reset Window	X	X	X	X	X	X
<Ctrl> + C	Cut Tool					X	X
<Ctrl> + M	Mill					X	X
<Ctrl> + F	Fast Mill						X
<Ctrl> + <Alt> + F8	Extended color scale: Adds 2 blue shades to distance area					X	X
<Ctrl> + <Alt> + F9	Restoration Morphology: Biogeneric detail setting		X	X		X	
<F1>	Help	X	X	X	X	X	X
<F5>	Auto-rotate model demo ("Turnfly") on/off		X	X	X	X	X
<F7>	(With scale tool active) Select entire restoration					X	
<F10>	Activate <Alt> shortcuts (underlined letters in menus)	X	X	X	X	X	X
<Shift> + P	Open Parameters dialog	X	X	X	X	X	X
<Space>	(With scale tool active) Select entire restoration					X	
<Space>	Toggle Margin mode: Auto-find, manual (Bluecam images only), manual w/ intensity image			X			